


Incoming
c/p/s/0075 *OK*

Consolidation Coal Emery Mine Subsidence Report for May 2007

- 5-8-07 No subsidence noticed over Panel 14 West. PB
- 5-19-07 No subsidence noticed over Panel 14 West. PB
- 5-21-07 No subsidence noticed over Panel 14 West. PB
- 5-31-07 Subsidence noticed over Panel 14 West. PB
- 6-4-07 1 inch cracks found above Panel 14 West where pillaring. Marked locations with GPS. PB



6-8-07

Few cracks over Panel 14 West pictures were taken. PB











6-13-07 Went to the surface with DOGM (Helfrich, Burton, and Christensen) and (Carter – landowner, Robertson – adjacent landowner, Knoop – JBR). All 3 springs SP-10, SP-11, and SP-12 were flowing. Two sets of cracks $\frac{1}{2}$ to $\frac{3}{4}$ inch wide were noticed across the road leading to the field. Landowner did mention at the South end of the long West Field the irrigation is not flowing to the end due to a high spot and low spot in the field. Walked the area with the land owner and could not find any cracks or signs of movement. However, area is above pillared out portion of the section.
RH